2007 ADS Stormwater Workshop January 19th, 2007

Geotechnical Engineering Design Pitfalls and Fundamentals of Ground Water/Surface Water Interaction

presented by Devo Seereeram, Ph.D., P.E.



Geotechnical Pitfalls in Stormwater Design



TOPICS

- 1. Dry Bottom Ponds Excavated into Clayey Soils
- 2. Pond Berm Failures & Flooding Consequences
- 3. Flooding of Land Locked Lakes
- 4. Land-Locked Basins Affected by Floridan Aquifer
- 5. Pavement Failure Due to Grades Cut into Water Table
- 6. Pavement Failure Due to Over Irrigation of Landscape Areas
- 7. Perched Water Table Due to Low Permeability Lot Fill
- 8. Seepage Through Pond Berms


TOPICS

- 9a. Water Table Altitude Can Change Significantly Over Short Distances
- 09b. Seepage Faces
- 10. Failure of Erosion Control Measures and Impact to Wetlands
- 11. Load Testing of Natural Depressions
- 12. Side Slope Failures Due to Storm-Induced Wave Action
- 13. Water Table Drawdown Impact Due to Ditching
- 14. Drought
- 15. Relic Sock Drains and Irrigation Pipes Leading to Unexplained "Spring Seepage" After Development



2007 ADS STORMWATER WORKSHOP


Dry Bottom Ponds Excavated into Clayey Soils



2007 ADS Stormwater Workshop Wekiva Run – Pond 1







2007 ADS Stormwater Workshop

Wekiva Run – Pond 2





Wekiva Run – Pond 3





2007 ADS STORMWATER WORKSHOP

Pond Berm Failures & Flooding Consequences











2007 ADS STORMWATER WORKSHOP

Flooding of Land Locked Lakes














Debary Plantation























2007 ADS Stormwater Workshop

Land-Locked Basins Affected by Floridan Aquifer

Lake Rexford and Lake Osage, Orange County













Lake Rexford and Lake Osage – Site Vicinity




Lake Rexford and Lake Osage




Lake Rexford and Lake Osage – Well Locations




Lake Rexford and Lake Osage -Lithostratigraphy



Lake Rexford and Lake Osage Potentiometric Surface Contours






Calvin Street and Crystal Cove Depressions, Deland











Crystal Cove, Deland Area




Crystal Cove, Deland Area




Crystal Cove, Deland Area



Calvin Street and Crystal Cove Depressions, Deland Area



Calvin Street and Crystal Cove Depressions, Deland Area



Calvin Street and Crystal Cove Depressions, Deland Area

2007 ADS Stormwater Workshop




Exhibit 3. All Floridan aquifer wells in DeLand area for period of record



2007 ADS Stormwater Workshop

Pavement Failure Due to Grades Cut into Water Table

Community Area - Reflections Subdivision in Ocoee



Community Area - Reflections Subdivision in Ocoee



Cool Spring Circle - Reflections Subdivision in Ocoee



Econ River Estates in East orange County





2007 ADS Stormwater Workshop

Pavement Failure Due to Over Irrigation of Landscape Areas

Central Florida Parkway













2007 ADS Stormwater Workshop

Perched Water Table Due to Low Permeability Lot Fill















2007 ADS Stormwater Workshop

Seepage Through Pond Berms

FDOT Saxon Pond



FDOT Saxon Pond




FDOT Saxon Pond























2007 ADS Stormwater Workshop

Water Table Altitude Can Change Significantly Over Short Distances

Robinson Hills



Robinson Hills





2007 ADS Stormwater Workshop

Seepage Faces

Steep upland adjacent to Lake Meadow in Ocoee





2007 ADS Stormwater Workshop

Failure of Erosion Control Measures and Impact to Wetlands

Site in Seminole County






2007 ADS Stormwater Workshop

Load Testing of Natural Depressions

Deerwood Apts in Ocala



Deerwood Apts in Ocala – Main Pond



Deerwood Apts in Ocala – Main Pond























2007 ADS Stormwater Workshop

Side Slope Failures Due to Storm-Induced Wave Action

CR 561 Clermont



CR 561 Clermont



2007 ADS Stormwater Workshop

Photo date: 2004 (Hurricane Jeanne)



2007 ADS Stormwater Workshop

Water Table Drawdown Impact Due to Ditching

Site in Brevard County




Site in Brevard County




Site in Brevard County



Site in Brevard County – Soil Cross Section, Transect 2




Site in Brevard County – Drawdown Predictions, Transect 2






Clermont Chain of Lakes – Lake Minnehaha



Clermont Chain of Lakes – CR 565A Bridge



Clermont Chain of Lakes – Lake Minneola



Clermont Chain of Lakes – CR 561





2007 ADS Stormwater Workshop

Relic Sock Drains and Irrigation Pipes Leading to Unexplained "Spring Seepage" After Development

Tully Wood Court



Tully Wood Court



Tully Wood Court

